

To Protect Your Warranty, Use Only ENERPAC Hydraulic Oil.

Enerpac recommends that all kit components be installed to insure optimum performance of the repaired product.




Figure 1, 50-Ton, Double-acting, Solid Plunger, Hydraulic Cylinder

Repair Parts List for Figure 1							
Item	Part Number	Qty.	Decription		Item	Part Number	Qty. Decription
1	L661028	2	Saddle Screw		13	★L339044	1 Retaining Ring
2	L345045	1	Saddle		14	CJ160900W -7000	1 Safety Valve (6,500-7,500 psi)
3	★ G732044	1	Wiper Ring		15	CR-40	2 Coupler
4	Y193044	1	Stop Ring		16	CJ92030	1 Cylinder
5	★B1235564	1	Back-Up Washer		17	CM162020	1 End Cao
6	★B1235803	1	O-Ring		18	CM163044	1 Stop Ring
7	M28044	1	Stop Ring		19	CL401271	1 Collar Thread Protector
8	★ B1238903	2	O-Ring		20	DC4453021	2 Hex Nut
9	CM164040	1	Plunger		22	B1141046	2 Cap Screw
10	L341107	3	Rod Bearing		23	CL926070	2 Handle
11	★L343108	2	Washer		25	CL1001489	2 Collar
12	★DC7079041	2	U-Cup				
★ Items included in and available only as part of Repair Kit RR-5013K1. (For Viton order kit RR5013KV.)							